

DPD-0863-61

10 February 1961

MEMORANDUM FOR : Chief, Operations Branch, DPD-DD/P

SUBJECT : Alterations of Air Section and
Air Maintenance Section Space

REFERENCE : Memorandum to C/MB/DPD from
COPS/DPD; dated 3 February 1961,
subject as above (DPD-0433-61)

I realize the cost estimate of \$26,150 for alterations of Air Section and Air Maintenance Section space appears to be staggering. However, when you stop to consider that you are paying GSA [REDACTED] an hour per man plus the cost of material and transportation of material, this cost is not out of line. This [REDACTED] is paid from the time of departure from the shop until return. Included in this is GSA overhead costs. A breakdown of the cost of this work is as follows:

1. New partitioning	\$ 1,600.00
2. Re-locating existing partitions	300.00
3. Removal of partitions	500.00
4. Installing new doors	300.00
5. Closing, securing and soundproofing existing doors	350.00
6. Soundproofing of briefing room	2,200.00
7. Drapes on four walls with track	3,500.00
8. Revamping electrical, telephone and air-conditioning water and drain lines	2,500.00
9. Air-conditioning entire area including five ton unit and duct work	13,000.00
10. Eight panel boards	1,500.00
11. Painting	500.00
TOTAL	\$26,150.00

DOCUMENT NO. _____
NO CHANGE IN CLASS. ☒
☐ DECLASSIFIED
CLASS. CHANGED TO: TS S C 2011
NEXT REVIEW DATE: _____
AUTH: RR 102
DATE: 10/14/81 REVIEWER: 064540

0 & 1 AC/DPD
ADMIN/DPD

ADMIN/DPD

1 - C/MB/DPD
1 - RI/DPD

DPD-DD/P

25X1A

25X1A

25X1A